

Timing Cover Ford Ranger 2.0 T8 2019-2021 Model JB3Q6019BA Replacement Repair

Basic Information

Place of Origin: Shanghai, China
Brand Name: TUNEMOUT
Certification: ISO9001
Model Number: JB3Q6019BA

• Minimum Order Quantity: 10

Price: USD 17.6-22.2/pcsPackaging Details: Original Package

• Delivery Time: 1-2 weeks

• Payment Terms: L/C,D/A,D/P,T/T,Western Union,MoneyGram

• Supply Ability: 10000 units per week



Product Specification

• OE Numbers: JB3Q-6019-BA, JB3Q-6509-BA,

JB3Q6019BA

• Type: Belt Cover Timing Chain Cover

• Condition: New

Engine Code: JB3Q-6019-BA
Warranty: 12 Months
Place Of Origin: Shanghai, China

• Highlight: Ford Ranger 2.0 T8 2019 Timing Cover,

Model JB3Q6019BA Timing Cover, Replacement Repair Timing Cover

Timing Cover Ford Ranger 2.0 T8 2019-2021 Model JB3Q6019BA Replacement Repair

Product Attributes

Attribute	Value
OE Numbers	JB3Q-6019-BA, JB3Q-6509-BA, JB3Q6019BA
Туре	Belt Cover Timing Chain Cover
Condition	New
Engine Code	JB3Q-6019-BA
Warranty	12 Months
Place of Origin	Shanghai, China

Ford Ranger 2.0 T8 Timing Chain Cover - Technical Specifications

Product Overview

Part Number: JB3Q6019BA (OEM: JB3Q-6019-BA)
Compatibility: 2019-2021 Ford Ranger 2.0 T8 (2WD/4WD)

Material: High-grade aluminum casting

Warranty: 12 months



Key Features

Precision Fit: Maintains original sealing surface for crankshaft/timing sensors

Protective Design: Shields against debris while ensuring oil containment

Installation Ready: Includes pre-installed threaded inserts and alignment dowels

Quality Assurance: 100% tested for cracks/warping before shipment

Technical Specifications

OEM References	JB3Q-6019-BA, JB3Q-6509-BA
Engine Code	JB3Q-6019-BA

Condition	Factory new
MOQ	10 pieces
Origin	Shanghai, China

Installation Notes

Required Components: Separate gasket set (Ford #CV6Z-6020-A)

Torque Specification: 10 N*m + 90° rotation

Common Failure Causes: Gasket shrinkage or casting porosity

FAQ

Q: 2020 Ranger 2.0 4×4 compatibility?

A: Yes - JB3Q6019BA fits all 2019-2021 Ranger 2.0 T8 configurations.

Q: Includes gaskets/bolts?

A: No (sold separately). Original bolts may be reused if undamaged.

Q: Oil leak causes?

A: Typically degraded gaskets or cover porosity. Replace both components.



shanghai junbo industrial co.,ltd



008618017883766



kenneth@tunemout.com



junboautoparts.com

No 3652, Caoan Road, Shanghai ,China