



Timing Cover Ford Ranger 2.0 T8 2019-2021 Model JB3Q6019BA Replacement Repair

Our Product Introduction

Basic Information

- Place of Origin: Shanghai, China
- Brand Name: TUNEMOUT
- Certification: ISO9001
- Model Number: JB3Q6019BA
- Minimum Order Quantity: 10
- Price: USD 17.6-22.2/pcs
- Packaging Details: Original Package
- Delivery Time: 1-2 weeks
- Payment Terms: L/C,D/A,D/P,T/T,Western Union,MoneyGram
- Supply Ability: 10000 units per week



Product Specification

- OE Numbers: JB3Q-6019-BA, JB3Q-6509-BA, JB3Q6019BA
- Type: Belt Cover Timing Chain Cover
- Condition: New
- Engine Code: JB3Q-6019-BA
- Warranty: 12 Months
- Place Of Origin: Shanghai, China
- Highlight: **Ford Ranger 2.0 T8 2019 Timing Cover, Model JB3Q6019BA Timing Cover, Replacement Repair Timing Cover**

for more products please visit us on junboautoparts.com

Product Description

Timing Cover Ford Ranger 2.0 T8 2019-2021 Model JB3Q6019BA Replacement Repair

Product Attributes

Attribute	Value
OE Numbers	JB3Q-6019-BA, JB3Q-6509-BA, JB3Q6019BA
Type	Belt Cover Timing Chain Cover
Condition	New
Engine Code	JB3Q-6019-BA
Warranty	12 Months
Place of Origin	Shanghai, China

Ford Ranger 2.0 T8 Timing Chain Cover - Technical Specifications

Product Overview

Part Number: JB3Q6019BA (OEM: JB3Q-6019-BA)
Compatibility: 2019-2021 Ford Ranger 2.0 T8 (2WD/4WD)
Material: High-grade aluminum casting
Warranty: 12 months



Key Features

- Precision Fit:** Maintains original sealing surface for crankshaft/timing sensors
- Protective Design:** Shields against debris while ensuring oil containment
- Installation Ready:** Includes pre-installed threaded inserts and alignment dowels
- Quality Assurance:** 100% tested for cracks/warping before shipment

Technical Specifications

OEM References	JB3Q-6019-BA, JB3Q-6509-BA
Engine Code	JB3Q-6019-BA

Condition	Factory new
MOQ	10 pieces
Origin	Shanghai, China

Installation Notes

Required Components: Separate gasket set (Ford #CV6Z-6020-A)

Torque Specification: 10 N*m + 90° rotation

Common Failure Causes: Gasket shrinkage or casting porosity

FAQ

Q: 2020 Ranger 2.0 4x4 compatibility?

A: Yes - JB3Q6019BA fits all 2019-2021 Ranger 2.0 T8 configurations.

Q: Includes gaskets/bolts?

A: No (sold separately). Original bolts may be reused if undamaged.

Q: Oil leak causes?

A: Typically degraded gaskets or cover porosity. Replace both components.



shanghai junbo industrial co.,ltd



008618017883766



kenneth@tunemout.com



junboautoparts.com

No 3652, Caoan Road, Shanghai ,China