

# JB3Q6019BA Timing Chain Cover For Ford Ranger 2.0 T8 2019-2021 JB3Q6019BA

# **Basic Information**

Place of Origin: Shanghai, China
Brand Name: TUNEMOUT
Certification: ISO9001
Model Number: JB3Q6019BA

• Minimum Order Quantity: 10

Price: USD 17.6-22.2/pcsPackaging Details: Original Package

• Delivery Time: 1-2 weeks

• Payment Terms: L/C,D/A,D/P,T/T,Western Union,MoneyGram

Supply Ability: 10000 units per week



# **Product Specification**

Color: Original Color

• MOQ: 10pcs

Brand: TUNEMOUTOEM: JB3Q6019BA

• Condition: New

Application: Auto Engine Parts

• Highlight: Ford Ranger timing chain cover,

JB3Q6019BA engine part, 2019-2021 Ford Ranger cover



# More Images



# **Product Description**

#### JB3Q6019BA Timing Chain Cover For Ford Ranger 2.0 T8 2019-2021

#### **Product Specifications**

Attribute	Value
Color	Original color
MOQ	10pcs
Brand	TUNEMOUT
OEM	JB3Q6019BA
Condition	New
Application	Auto Engine Parts

#### **Key Features**

OE Numbers: JB3Q-6019-BA, JB3Q-6509-BA, JB3Q6019BA

Type: Belt Cover Timing Chain Cover

Condition: New

Engine Code: JB3Q-6019-BA

Warranty: 12 Months

Place of Origin: Shanghai, China Purpose: Replacement/repair

**Brand: TUNEMOUT** 

Model Number: JB3Q-6019-BA

#### **Product Description**

This OEM timing chain cover for the 2019-2021 Ford Ranger 2.0 T8 (part number JB3Q6019BA) is an exact-match replacement cast from durable aluminum. It features the original sealing surface for proper fitment of crankshaft and timing sensors. The cover effectively shields timing components from dirt, oil splash, and road debris while maintaining proper oil containment. Pre-installed threaded inserts and alignment dowels simplify installation. Each unit undergoes rigorous inspection for cracks, warping, or porosity before shipment. Note: Gaskets and bolts are sold separately.

## **Packaging Information**

Selling Units: Single item

#### **Frequently Asked Questions**

## Q: Will this cover fit my 2020 Ranger 2.0 4×4?

A: Yes. JB3Q6019BA is the correct Ford part number for all 2019-2021 Ranger 2.0 T8 variants (2WD & 4WD).

#### Q: Does the cover come with gaskets or bolts?

A: No, it is supplied bare to keep cost down. You can reuse your original bolts if undamaged, or order the Ford gasket set separately (part #CV6Z-6020-A).

## Q: Why is my old cover leaking oil?

A: Most leaks stem from gasket shrinkage or cover porosity. Replace the cover and install a new gasket with proper torque sequence (10 N\*m + 90°) to eliminate future leaks.



shanghai junbo industrial co.,ltd



008618017883766



kenneth@tunemout.com

