

Clutch Release Bearing Ford Ranger 2.0L 2019-2021 JB3R-7A543-AA Long-life Steel

Basic Information

. Place of Origin: Shanghai, China TUNEMOUT . Brand Name: ISO9001 · Certification:

JB3R-7A543-AA Model Number:

• Minimum Order Quantity:

• Price: USD 40.11-42.35/PCS · Packaging Details: Original Package

• Delivery Time: 1-2 weeks

Payment Terms: L/C,D/A,D/P,T/T,Western Union,MoneyGram

. Supply Ability: 10000 units per week



Product Specification

· Color: Original Color 10PCS MOQ: **TUNEMOUT** . Brand: JB3R7A543AA • OEM: · Condition: **New Condition**

Application: Auto Transmission Parts

• Highlight: JB3R-7A543-AA Clutch Release Bearing,

Ford Ranger 2.0L Clutch Release Bearing,

Long-life Steel Clutch Release Bearing



More Images



Clutch Release Bearing Ford Ranger 2.0L 2019-2021 JB3R-7A543-AA Long-life Steel

Product Specifications

Attribute	Value
Brand	TUNEMOUT
OEM Number	JB3R7A543AA
Condition	New
Application	Auto Transmission Parts
Minimum Order Quantity	10PCS

Key Features

Genuine Ford replacement part (OE #JB3R-7A543-AA)

Specifically designed for 2019-2021 Ford Ranger 2.0L models (including Bi-Turbo)

High-quality steel bearing construction for durability

Ensures smooth clutch disengagement

Quiet operation

6-month warranty

Compatibility & Technical Details

Fitment: Ford Ranger 2019-2021 models (verify VIN for other years)

OE Numbers: 5100235100, JB3R-7A564-AA

Place of Origin: Shanghai, China Package Size: 20×5×10 cm

Weight: 0.350 kg

Ordering Information

Delivery Time: 7-14 days

Payment Methods: TT, Western Union, PayPal Packaging: Standard protective packaging

Installation Notes

Recommended to use clutch alignment tool during installation for proper fitment.

Frequently Asked Questions

Q: Is this bearing only compatible with 2019-2021 Ranger 2.0L models?

A: Yes, please verify your VIN for compatibility with other model years.

Q: Are special tools required for installation?

A: We recommend using a clutch alignment tool during installation for proper fitment.

Q: What are the signs of a failing clutch release bearing?

A: Common symptoms include squealing noises when the pedal is pressed or increased pedal resistance. If you notice these signs, inspect and replace the bearing promptly.



shanghai junbo industrial co.,ltd



008618017883766



